



Wiring MJoy16-C1 controls directly to MJoy16 board


Column 3
Column 2
Header Pins
Switch A1
joins here
Column 1
Row A
Column 1
Negative end of
diode connects
to pin
Diode is standing on end

Negative end of diode goes to the Rows
Positive to the Columns

