

Arduino mega2560	Motommonster	Potentiometer's	Power supply	Motors
PWM 4	4			
PWM 5	5			
PWM 6	6			
PWM 7	7			
PWM 8	8			
PWM 9	9			
5v	5v	5v upper side		
GND	GND	GND down side		
Analog in 4		Left pot center		
Analog in 5		Right pot center		
	A1			Left motor +
	B1			Left motor -
	A2			Right motor +
	B2			right motor -
	+		12V	
	-		0V	