



- ① Motor mount
- ② BEARING block
- ③ Nut holder
- ④ LOSE (LOL)
- ⑤ Top bearing block
- ⑥ BRIDGE
- ⑦ PRECISION ROUND RAIL
- ⑧ BAL SCREW
- ⑨ BAL NUT
- ⑩ LINEAR BEARINGS
- ⑫ Top bearing
- ⑬ UNDER BEARING